



Inspection Report

UNIVERSITY OF TEXAS

Customer ID: 1477

Certificate: 74-R-0078

Site: 001

HEALTH SCIENCE CENTER AT TYLER - VIVARIUM

HEALTH SCIENCE CENTER AT TYLER - VIVARIUM

11937 U S HWY 271

Type: ROUTINE INSPECTION

TYLER, TX 75708

Date: Mar-24-2011

3.51 (d)

FACILITIES, INDOOR.

(d) Interior surfaces. The interior building surfaces of indoor housing facilities shall be constructed and maintained so that they are substantially impervious to moisture and may be readily sanitized.

The ceiling over the cage wash and the wall of the storage area contained flaking paint. The indoor facility shall be constructed and maintained so that they are substantially impervious to moisture and may be readily sanitized.

TO BE CORRECTED BY: 04/24/2011.

Note: During the exit briefing it was discussed with management that they should consider purchasing feed from vendors that label their feed with a production date.

This routine inspection and exit briefing were conducted with management and USDA VMO, Earnest H. Johnson.

Prepared By:

EARNEST H JOHNSON, D.V.M. USDA, APHIS, Animal Care

Date:

Title: VETERINARY MEDICAL OFFICER Inspector 4048

Mar-24-2011

Received By:

(b)(6),(b)(7)(c)

Date:

Title:

Mar-24-2011